





As one of the world's leading suppliers of safety and protective equipment our goal is to ensure that we satisfy your needs through the provision of exceptional leadership, expertise, quality and service excellence. Our success is measured by your success. If we can make your life and that of your workforce easier, healthier, safer and more productive we are moving in the right direction.

We believe that health and safety is first and foremost about safeguarding worker welfare. A secure, safe working environment is paramount in any business. But we also believe that improving worker protection, comfort and productivity is a more ambitious goal. One we firmly believe in.

At 3M we don't take safety for granted. The health and welfare of your workforce depends on it. So by working in association with skilled safety practitioners, partners and customers, our people are committed to ensuring that we help you create an environment that protects your workforce – effectively, efficiently and economically.

Your success is our achievement. To deliver on our commitment requires a culture of accountability, customer inspired innovation, knowledge and expertise, fuelled by a deep understanding of your needs and the safety needs of your workforce.

With our global technology, manufacturing and knowledge network we do more than simply develop products that ensure your workforce can operate in safety and comfort. We go further to provide good design, cross-over compatibility, expertise, comprehensive support and continuously evolving a range of product options.



Continuously inspired by welders

Customer support

You can buy 3M confident in the knowledge that our products will do the job and more. You can also rest assured that our product range is backed by first class support materials and advice, so you'll always know where to turn.

For advice, information and technical support on the selection and use of 3M Welding Equipment contact the 3M Health and Safety Helpline.

A range of technical literature, posters, selection guides and fact sheets are freely available from the 3M Health and Safety Helpline to help you with your safety requirements.

More information on products and services from 3M is available from our website. Downloads, legislation, special offers, contact 3M, where to buy, maintenance packs and much more can all be found at: www.3M.co.uk/speedglas









The brand that introduced the ADF



The innovator of the 3M[™] Speedglas[™] Auto-Darkening Welding Filter completed his thesis in the shipyards of Sweden studying ways to protect welders' eyes and skin from harmful UV radiation. The studies were conducted more than 30 years ago and resulted in the first prototype of an auto-darkening welding filter, a combination of liquid crystal elements, polarizers and electronics.

3M Auto-Darkening Filters

- The brand that introduced the ADF
- A quick guide to all our auto-darkening welding filters

3M[™] Speedglas[™] Welding Shields

- 3M[™] Speedglas[™] 100 Welding Shields
- 3M[™] Speedglas[™] 9100 Welding Shields
- 3M[™] Speedglas[™] 9002D Welding Shield
- 3M[™] Speedglas[™] SL Welding Shield



How ADFs work

The key point to remember with 3M™ Speedglas™ auto-darkening welding filters (or ADFs) is consistency. They enable constant, comfortable vision, they provide protection from ultraviolet and infrared (UV/IR) radiation and they consistently auto-switch from clear to dark and back again, in just the way the welder wants.



Before

With the shield in the safe down position, the welder has a clear view through the welding filter. Both hands are free and the electrode can be precisely positioned.



During

Within 0.1 milliseconds of the arc strike, the filter has switched to the dark state.



After

The filter automatically returns to the clear state after welding is complete, allowing for immediate and safe inspection of the weld pool, as well as preparation for the next weld.

Technical data Speedglas Welding Shield with ADF	3M™ Speedglas™ 100 Shield Black and Graphics Edition	3M™ Speedglas™ 9000 Shield		3M™ Speedglas™ SL Shield	3M™ Speedglas™ 9100 Shield		Shield	
Welding Filter Options	100V ADF (variable)	9002D ADF (dual)	9002V ADF (variable)	9002X ADF (variable)	SL ADF (variable)	9100V ADF (variable)	9100X ADF (variable)	9100XX ADF (variable)
Viewing area	44 x 93mm	42 x 93mm	42 x 93mm	55 x 107mm	42 x 93mm	45 x 93mm	54 x 107mm	73 x 107mm
Weight (complete helmet incl ADF)	510g	710g	750g	770g	360g	510*g	520*g	545*g
Dark state	Shade 8-12	Shade 9/11	Shade	9-13	Shade 8-12		Shade 5, 8, 9-13	
Light state	Shade 3	Shade 3	Sha	de 3	Shade 3	Shade 3		
UV / IR Protection	Shade 12 (permanent)	Shade 13 (permanent)		Shade 12 (permanent)	Shade 13 (permanent)			
Auto ON	No	No		Yes	No			
Switching time, light - dark	0,1 ms (+23°C)	0,4 ms (+23°C)	0,4 ms (+23°C) 0,1 ms (+23°C)		0,1 ms (+23°C)	0,1 ms (+23°C)		
Delay (switching time, dark - light)	100-250 ms	100-200 ms	100-200 ms 60-500 ms		60-250 ms	40-1300 ms		
SideWindows option	No		Yes		No		Yes	
Exhaust vents	No		Yes		No		Yes	
Hard hat option	Yes	Yes	Yes	Yes	No		No	
Solar cell	No	No	No	Yes	No	Yes	Yes	No
Number of sensors (arc detection)	2	2	2	2	2	3	3	3
Battery lifetime	1 500 hours	1 500 hours	1 500 hours	3 000 hours	1 500 hours	2 800 hours	2 500 hours	2 000 hour

A quick guide to our Auto-Darkening Welding Filters

The $3M^{\mathsf{TM}}$ Speedglas[™] Auto-Darkening Filter (ADF) was one of the first of its type on the market, bringing a new standard to eye protection and comfort for welders. Today there is a great family of $3M^{\mathsf{TM}}$ Speedglas[™] Welding Shields, each model with its specific series of welding filters.

Before you select a model, ask yourself:

- · How will I use my ADF?
- Do I occasionally change welding process/shade number?
- This is a long term investment. A variable welding filter offers more flexible features for new working conditions.

Filter Guide

There are a few parameters that affects the performance of an autodarkening welding filter like the type of welding machine, working environments etc.

The table below is a general guide to the various models of 3M[™] Speedglas[™] Auto-Darkening Welding Filters:

Optimised Suitable Not recommended	Speedglas 9100XX	Speedglas 9100X	Speedglas 9100V	Speedglas SL	Speedglas 9002X	Speedglas 9002V	Speedglas 9002D	Speedglas 100V
Dark state	Shade 5, 8, 9-13 (variable)	Shade 5, 8, 9-13 (variable)	Shade 5, 8, 9-13 (variable)	Shade 8 -12 (variable)	Shade 9-13 (variable)	Shade 9-13 (variable)	Shade 9/11 (dual)	Shade 8 -12 (variable)
MMAW (Electrode)								
MIG/MAG								
TIG (>20A)								
TIG (1A-20A)								
Plasma (welding and cutting)								
Risk of hidden arc								
Tack welding								
Grinding								

For assistance with choosing the right ADF, please call the 3M Safety Helpline on 0870 60 800 60 (UK) or 1 800 320 500 (Ireland)



3M[™] Speedglas[™] 100 Welding Shields



The highly-affordable 3M[™] Speedglas[™] 100 Welding Filter has excellent optical quality, reliable light-to-dark switching, and can be used with most arc welding processes, such as stick (MMA), MIG/MAG, and many TIG applications.

The easy-to-use 3M[™] Speedglas[™] 100 welding shield is the ideal 'first' auto-darkening shield for users who weld infrequently but can benefit from the ability to always see clearly with their welding protection in place. In addition to the black shield there are 10 graphic shields available – all with specific identity. Also available is the 3M[™] Speedglas[™] 100 Series hard hat option for mandatory head protection areas.

Features and Benefits:

• UV/IR protection shade 12 permanent

Variable Shade Welding Filters (100V)

- Three selectable sensitivity settings:

 a normal setting used for most types
 of welding, a setting for other welders
 working nearby and a setting for low-current or stable arc welding
- Five user-selectable dark shades 8-12
- · Switching time light-dark 0,1 ms



3M[™] Speedglas[™] 100 Blaze Welding Shield

Classification 1/1/2 Conforms to EN 379

3M Speedglas 100 Welding Shields Graphic Editions



Chrome



Tribal



Mechanical Skull



Trojan Warrior



Blaze 75 12 20



Aces High



75 21 20



Jewel Skull 75 19 20



Steel Rose




Wild'n'Pink



3M™ Sı









75 00 20 : **3M**[™] **Speedglas**[™] **100V Filter** Viewing area: 44 x 93mm



3M[™] Speedglas[™] 9100 Series Welding Shields

Optimise your welding comfort, coverage and control. The 3M[™] Speedglas[™] 9100 Welding Shield features a head suspension system that profiles your unique head shape for a secure, stable fit.

High comfort head suspension

Two crown straps gently saddle the top of the head for increased shield stability and better weight distribution. Both straps are adjustable to fit virtually all head shapes and sizes.

The back portion of the headband is self-adjusting and swivels to fit different head shapes. When wearing a cap backwards you simply turn the back portion upside-down.

The headband can also be manually tightened to your personal preference. The smooth ratchet mechanism allows for precise tightening control.

A snap adjustment allows you to set the shield at 9 different angles.

The front of the headband self-adjusts to match your forehead. Pressure is evenly distributed to sets of twin pads to fit the exact shape of your head.

Four settings let you determine the distance between your face and the shield. This allows you to keep the shield as close as possible to your face for a greater view and reduces the load on your neck muscles.

Small, Medium or Large?
You can adjust the width of the head suspension to your own head size – from 50cm to 64cm.

We've lowered the centre of gravity to be just above your ears! This makes the shield more stable in both the up and down positions, as well as reducing the leveraged strain on your neck. Large, rubber, overmoulded knobs make it easy to adjust the up-and-down pivot action, even when wearing gloves.

More comfort when raised

Lifted into the raised position, the shields "high point" is lower than many other shields. The smooth up-and-down pivot action can be "locked" in the up position – a light pull lowers the shield back down again.

Excellent optics, bigger view

The 3M[™] Speedglas[™] 9100 Series Welding Filters continue our tradition of outstanding optical quality, including uniform shading and minimal distortion across the entire filter viewing area.

Wider field of view

Introducing the 3M[™] Speedglas[™] 9100FX Welding Shield, a flip-up combination of an ADF welding shield and a protective visor.

Comfortable protection for safer welders

The 3M[™] Speedglas[™] 9100 Series Welding Shields are available either with ADF in a fixed position or with the ADF in a flip-up visor which can be lifted to leave a clear visor.

The $3M^{\text{™}}$ Speedglas[™] 9100FX Series Welding Shield features a flip-up combination of an auto-darkening welding shield and a protective visor. Not only is the viewing area of the shield larger than on previous models $-17 \times 10 \text{cm}$ – the geometry of the shield has also been redesigned to increase peripheral vision.

Features and Benefits:

- 30% larger viewing area than any other Speedglas welding filter (9100XX)
- Adjustable sensitivity of arc detection
- Seven variable dark shades (5, 8, 9-13), including shades for gas welding, micro-plasma and low-amp TIG
- Exclusive shade 5 SideWindows option
- The big 17x10cm clear protective visor is curved, increasing your peripheral vision
- Increased coverage for ear and neck
- · Exhaled air is channelled out via side exhaust vent



3M[™] Speedglas $^{™}$ 9100 Welding Shield

Classification 1/1/1/2 Conforms to EN 175 level B and EN 379 Light state shade 3

Part Numbers:

50 18 05 : **9100** Shield with **9100V** Filter 50 18 15 : **9100** Shield with **9100X** Filter 50 18 25 : **9100** Shield with **9100XX** Filter

3M[™] Speedglas [™] 9100FX Welding Shield

Classification 1/1/1/2 Conforms to EN 175 level B and EN 379 Light state shade 3

Part Numbers:

54 18 05 : **9100FX Shield with 9100V Filter** 54 18 15 : **9100FX Shield with 9100X Filter** 54 18 25 : **9100FX Shield with 9100XX Filter**

3M™ Speedglas™ 9100 Filter Options:

50 00 25 : 3M[™] Speedglas[™] 9100XX Filter 50 00 15 : 3M[™] Speedglas[™] 9100X Filter 50 00 05 : 3M[™] Speedglas[™] 9100V Filter

3M™ Speedglas™ 9100 Consumables:

 $52\,60\,00$: outer protection plate standard (pck 10)

 $52\,70\,00$: outer protection plate scratch resistant (pck 10)

16 80 15 : 9100 sweatband (pck 3)

All shields fit well with 3M Respiratory Protection







3M[™] Speedglas[™] 9002D Welding Shield

With a dual shade filter and two sensitivity levels, the $3M^{TM}$ Speedglas TM 9002D offers the welder an excellent choice of settings. The 3M Speedglas 9002D Welding Shield features side windows and CO_2 reduction vents for improved comfort. The Speedglas 9000 Welding Shield is also available with a safety helmet, especially designed for welders working in areas with overhead hazards.

Features and Benefits:

- Available as complete shield with Speedglas 9002D welding filter, shade 9/11 (dual). The 9002V and 9002X filters can still be ordered as spares
- Speedglas SideWindows
- Exhaust vents
- Light state shade 3
- Switching time light-dark 0.4ms (+23°C)



3M[™] **Speedglas**[™] **9002D Welding Shield** Classification 1/2/2

Conforms to EN 379, EN 175 level F

40 18 40 : 9002 Shield with 9002D Filter

3M™ Speedglas™ 9002 Consumables 42 60 00 : outer protection plate standard (pck 10)

 $42\ 70\ 00$: outer protection plate scratch resistant (pck 10)

16 90 01 : Throat cover, Teca Weld



3M[™] Speedglas[™] Welding Filter Options:

40 00 80 : **3M**[™] **Speedglas**[™] **9002X Filter** Viewing area: 55 x 107mm

40 00 70 : **3M**[™] **Speedglas**[™] **9002V Filter** Viewing area: 42 x 93mm

40 00 40 : **3M**[™] **Speedglas**[™] **9002D Filter** Viewing area: 42 x 93mm





48 38 00 : **3M**[™] **Speedglas**[™] **9000 ProTop Welding Shield**

Classification 1/1/1 Conforms to EN 379, EN 175

3M[™] Speedglas[™] ProTop Consumables

19 67 05 : Safety helmet white, other colours upon request

19 71 50 : Safety helmet assembly parts

3M[™] Speedglas[™] SL Welding Shield

Welders have asked for two things in personal protection: lighter weight and more comfort. Our challenges in designing this shield were to significantly reduce its weight, while maintaining the performance and protection that welders worldwide have come to expect in every Speedglas product. The result of our efforts: a 360 gram auto-darkening welding shield.

Features and Benefits:

The Shield: stronger, thinner

- Strong lightweight material with excellent protection and coverage
- Non-absorbent material, that retains its performance in high humidity
- Back-and-forth adjustments allow for better fit and safety
- Ideal for tight spaces

Tit Viit

70 11 20 : 3M[™] Speedglas[™] SL Welding Shield

Classification 1/1/1/2 Conforms to EN 379, EN 175 level F

Auto-Darkening Welding Filter

- For most arc welding processes such as MMA, MIG/MAG, TIG and plasma welding
- Viewing area 42 x 93mm
- Light state shade 3
- Variable dark shade 8-12
- Switching time light-dark 0,1 ms (+23°C)

The Headband: Fits better, feels cooler

- A pattern of holes for breathability and better conformity to the welder's head
- Accommodates smaller head sizes; its full range is from 50cm to 64cm



3M™ Speedglas™ SL Consumables:

70 00 20 : Speedglas SL Auto-Darkening Filter Variable 8-12

 $72\ 60\ 00$: Speedglas SL Outer Protection Plate Standard (pk 5)

42 80 20 : **Speedglas Inner Protection Plate (ADF)**

16 80 10 : Sweatband, fleecy cotton

Performance and Comfort go hand in hand



Not even the best protective equipment will be used all day if it's not comfortable. 3M[™] Speedglas[™] Welding products are always designed with user comfort and performance in mind.

Obviously, good general ventilation is required for all working environments. To capture welding fumes, local exhaust ventilation and "on-gun, fume-extractors" are typically used.

In addition to local exhaust ventilation, welders often require respiratory protective equipment to further reduce exposure to contaminants.

- A general guide to respiratory protection
- 3M[™] Speedglas[™] 9100 Air / FX Air Powered & Supplied Air Respirators
- Care and Maintenance



A general guide to respiratory protection

Welding generates harmful airborne particles and gases known to cause short and long term health problems for welders. Respiratory Protective Equipment (RPE) may be used to help reduce exposure to these hazards.

Two types of RPE are used to protect welders:



Ventilation of the work area is important to help reduce the airborne concentration of contaminants and to ensure that the oxygen in the air is maintained at a safe level. Oxygen deficiency (i.e. <19.5% oxygen) can occur when welding in poorly ventilated areas or confined spaces. 3M do not offer RPE for use in oxygen deficient atmospheres.

The protection offered by RPE depends on the type of device and, if applicable, the filters fitted to it.

The levels of protection of 3M RPE for welders are listed in the table below. The Assigned Protection Factor (APF) for the equipment is published by the Health and Safety Executive in its book HSG-53. An APF of 20 indicates equipment that, when used properly, will reduce exposure by a factor of 20.

		Filtering devices						
Model	9925/9928	7500 with P2 filters	7500 with P3 filters	Adflo with Speedglas welding shields	Fresh-air C with Speedglas welding shields			
Туре	Disposable Respirator	Reusable Respirator	Reusable Respirator	Powered Air Respirator	Supplied Air Respirator			
APF	10	10	20	20 or 40 [†]	20 or 40 [†]			
Additional protection	Ozone up to 10xWEL* and nuisance level** organic vapours	Options available for Ozone up to 10xWEL* and nuisance level** gases/ vapours	Options available for Ozone up to 10xWEL* and nuisance level** gases/ vapours	Options available for gases and vapours				
*WEL = Workplace Exposure Limit **Nuisance level = below WEL †APF of 40 with 9100FX Air. APF of 20 with 9100 Air								



Filtering devices

Welders requiring respiratory protection need particle filters to capture metal fumes. In addition they may need gas and vapour filters depending on the type of work and the hazards generated. Harmful gases and vapours may be generated by ultraviolet light from the arc reacting with the air or by the burning of coatings or contamination on the metal.

Filtering devices can be either disposable or reusable:

Disposable respirators - e.g. 3M[™] 9925/9928 Reusable half face masks - e.g. 3M[™] 7500 Reusable powered respirators - e.g. 3M[™] Adflo

The options for gas and vapour filters are:

Filter type	A	В	E		
Description	Organic vapours, boiling point >65°C with good warning properties (taste and smell)	Inorganic gases/vapours with good warning properties (taste and smell)	Acid gases with good warning properties (taste and smell)		
Examples	Many common solvents, degreasants and thinners	Chlorine	Hydrogen chloride		
Note: Not all gases and vapours can be captured by filters. Check at www.3M.co.uk/selectrespirator					

Supplied air devices

3M[™] Fresh-air C protects welders by feeding breathable quality air from a compressor into a 3M[™] Speedglas[™] welding shield. It may be used when a supplied air device is preferred to a filtering device or against gases or vapours that cannot be filtered.

3M Air Quality Testing Service

The COSHH Regulations require that the air provided to supplied air devices should be of breathable quality and of sufficient, constant flow and pressure to provide adequate protection.

The 3M Air Quality Engineers will:

- ► test the air at several positions
- ▶ suggest measures and give sound advice if the air does not meet requirements
- ▶ issue a certificate should the air meet requirements for Breathable Quality Air

For more details see page 22



3M[™] Speedglas[™] 9100 Welding Systems

Improved Respiratory Protection - TH3

The New 3M[™] Speedglas[™] 9100 FX Air Welding Shields offer the highest respiratory protection - TH3 and excellent vision in the flip-up mode. It readily connects to 2 different air delivery units:

3M[™] Adflo[™] Powered Air Turbo
 3M[™] Fresh-Air C Supplied Air Regulator

The exclusive "stackable" configuration of the Adflo turbo unit means that the gas filter can be stacked onto the particle filter for additional protection from specific organic, inorganic and acidic gases and vapours.

Features and Benefits:

An Adaptable System

With the right type of filter, Adflo
 effectively protects against both particles
 and gases – all in one system. The filters
 can be replaced selectively: you don't need
 to change all filters at the same time

Filter Indicator -

 As soon as you turn on your Adflo powered air respirator a display indicates the status of the particle filter

Airflow

 For hot humid jobs the user can increase the airflow from 170 l/min to 200 l/min

Main Systems Part Numbers

- 54 66 05 : 9100FX Shield with 9100V ADF and Adflo
- 54 66 15 : 9100FX Shield with 9100X ADF and Adflo
- 54 66 25 : 9100FX Shield with 9100XX ADF and Adflo
- 56 66 05: 9100 Shield with 9100V ADF and Adflo
- 56 66 15 : 9100 Shield with 9100X ADF and Adflo
- 56 66 25 : 9100 Shield with 9100XX ADF and Adflo



Also available:

3M[™] **Speedglas**[™] **9100 Air Welding System** Assigned protection factor 20

Common Consumables:

83 71 00 : Adflo Particle Filter 83 60 10 : Adflo Prefilter (pck 5) 83 72 42 : Adflo Gas Filter A1B1E1 83 71 10 : Odour Filter, Holder & Pad 83 71 20 : Replacement Odour Filter Pad

83 60 00 : Spark Arrestor

83 40 16 : **Self-Adjusting Breathing Tube** 83 40 17 : **Heavy Duty Breathing Tube**



3M[™] Speedglas[™] 9100 Welding Shield with 3M[™] Fresh-air C Compressed Air Regulator

For highly-contaminated welding environments, you may use the 3M Fresh-air C compressed air respiratory system with a 3M[™] Speedglas[™] Welding Shield. The belt-mounted regulator connects to an approved air hose with a quick release connector system.

Features and Benefits:

Adjustable Air Flow

 The lightweight, belt mounted regulator allows the user to adjust the airflow from 160 to 300 litres per minute, making Fresh-air C ideal for hot and strenuous work

- · Air pressure 4-10 bar
- The exclusive airflow pattern evenly distributes filtered air throughout the entire breathing zone of the shield
- The soft, flexible face seal creates a positive pressure environment within the shield, keeping the surrounding pollutants at bay

3M™ Speedglas™ 9100 Air System Conforms to EN 14594 Class 2B Assigned protection factor 20

Comfort Belt -


Polypropylene 78 -150cm

Air Supply


- The air supply must be air of breathable quality meeting the requirements of EN12021
- The 3M[™] Aircare[™] filtration systems may be used to remove particles and odours.

Ranges

- 56 88 00 : 3M[™] Speedglas[™] 9100 Air with Fresh-air C Regulator without ADF*
- 54 88 00 : 3M[™] Speedglas[™] 9100FX Air with Fresh-air C Regulator without ADF*



Conforms to EN 14594 Class 3B Assigned protection factor 40



80 60 00 : Comfort Belt

85 30 64 : Air Hose

53 41 00 : **Face Seal**

83 40 16 : **Self-Adjusting Breathing Tube** 83 40 17 : **Heavy Duty Breathing Tube**

52 60 00 : Speedglas Outer Protection

Plate standard (pck 5)

16 80 15 : **Speedglas 9100 Sweatband**

(pck 3

^{*} Auto-Darkening Filter

3M[™] Personal Protective Equipment

3M offers you a wide range of personal protective equipment including maintenance free particulate respirators, reusable respirators, eyewear and hearing protection for the widest range of industrial applications, with unequalled pedigree, gained in the toughest conditions.

The 3M[™] Speedglas[™] 9100 Welding Shield and 3M[™] Speedglas[™] 100 Graphic Shield designs work well with most 3M[™] maintenance free respirators that provide protecton against hazardous welding particles. The products selected below are those that typically fit well inside the shield. They are well suited for the airborne hazards often found when welding.

Suggested models of respirators		Description	Approval	Part No.
3M™ 4000 Series Respirator		The 3M 4000 Series are a range of ready-to-use, maintenance-free half masks designed for effective and comfortable protection against a combination of many gases, vapours and particulates.	EN 405:2001	4251 - FFA1P2D 4255 - FFA2P3D 4277 - FFABE1P3D 4279 - FFABEK1P3D
3M™ 7500 Series Half Masks		The 3M 7500 Series Half Masks have set a new standard in introducing the highest levels of comfort to half mask respirators. With the 3M™ 2000 Series particle filters, the 7500 Half Mask fits comfortably inside the Speedglas 9100 shield.	EN140:1998	7501 - small 7502 - medium 7503 - large
3M™ 2128 and 2138 Series Filters	M 720 Garan Ca Ca Ca Ca Ca Ca Ca Ca Ca Ca Ca Ca Ca	The 3M 2128 and 2138 Series Filters offer particulate protection and additional nuisance level protection against organic vapours and acid gases. Both filters fit the 3M 7500 Series Half Masks.	EN143:2000 P2 R EN143:2000 P3 R	2128 2138
3M [™] 9925 or 9928 Particle Respirator		Maintenance Free Particulate Respirator for protection against fine dust, oil and water-based mists, metal fume and ozone. The 3M™ Cool Flow™ Valve reduces heat build up to offer comfortable protection, particularly in hot and humid environments.	EN149:2001 FFP2	9925 9928
3M™ 9922 Speciality Respirator		The 3M 9922 Particulate Respirator offers relief against fine dusts, oil and water-based mists and nuisance levels of organic vapours from solvents, degreasers and resins. It also provides protection against respiratory hazards during welding such as welding fume and ozone gas.	EN149:2001 FFP2	9922

Contact the 3M Health and Safety Helpline on **0870 60 800 60** (UK) or **1 800 320 500** (Ireland) for further advice



3M[™] Hearing Protection

Model	Description	Approval	Part Number
3M [™] 1310 Cap Banded Earplugs	The unique flexible band allows for easy manipulation and together with the soft round shape foam ear plugs provides reduced pressure and a comfortable seal.		1310
E·A·R [™] Classic [™] Ear plugs	E·A·R™ Classic Earplugs are made from a soft energy absorbing polymer foam which provides excellent hearing protection.		PP-01-002 : Pillowpack FP-01-000 : 5 pair PD-01-001 : One Touch Refill PD-01-009 : One Touch Top Up AM-01-000 : Classic Small
3M [™] 1100 Earplugs	The soft foam material provides maximum comfort and low pressure inside the ear.		1100 : Uncorded 1110 : Corded
3M [™] E·A·R [™] Push-Ins [™] Earplugs	The E·A·R™ Push-Ins™ Earplugs revolutionise hearing protection with more advantages than many other foam earplugs. No roll down is required, a gentle push is all it takes.	EN 352-2	EX-01-021 : Uncorded EX-01-020 : Corded
3M [™] E·A·R [™] Ultrafit [™] Corded Earplugs	For occasion when the convenience and permanence of a pre-moulded earplug is more suitable for your requirements.	EN 352-2	UF-01-00
Peltor™ Optime™ I Earmuff	Peltor Optime I Earmuff offers versatile protection and is very lightweight providing high wearer comfort. It combines a low profile with generous inner depth which makes it easy to combine with other equipment, allowing the ear to rest comfortably.	EN 352-3	H510B : Neckband H510A : Headband H510F : Folding Headband H510P3 : Helmet Attachment
Peltor™ Optime™ II Earmuff	Peltor Optime II Earmuff has been developed for demanding noisy environments and muffles even extremely low frequencies to a maximum degree.	EN 352-3	H520B: Neckband H520A: Headband H520F: Folding Headband H520P3: Helmet Attachment
Peltor™ Optime™ III Earmuff	Peltor Optime III Earmuff is a high performance hearing protector and has been developed for use in extremely noisy environments.	EN 352-3	H540B : Neckband H540A : Headband H540P3 : Helmet Attachment

3M[™] Coveralls

3M [™] 4520 Protective Coverall Type 5/6	Lightweight protection for all day comfort with breathable material for extra comfort and reduced heat stress.	Typical Applications Light duty maintenance Asbestos handling Abattoirs/Farming Construction work Wood/Metal processing
3M [™] 4540+ Protective Coverall Type 5/6	Combined performance and comfort offering excellent robustness and low linting properties.	Typical Applications Paint Spraying Asbestos handling Light-duty industrial cleaning and maintenance Pharmaceutical processing

3M[™] Eyewear

	Model		Description	Approval	Part Number
	3M [™] Virtua [™] AP Spectacles		Protection never looked so affordable. The new 3M™ Virtua™ AP features a graceful, unisex styling and lightweight comfort to help promote compliance.	EN 166 1.F	Lens Colour Product Code 71512-00000M 71512-
ECTACLES	3M™ 2720 Series Spectacles		Cost-effective protection and comfort. 3M [™] 2720 Classic Line Spectacles are lightweight and offer the wearer high levels of comfort together with reliable protection. They are available in 3 lens options.	EN 166:2001 1.FT	Lens Colour Product Code
3M CLASSIC SPECTACLES	3M [™] 2820 Series Spectacles		Safety with style. Very lightweight, sleek and modern design offering excellent coverage and field of vision.	EN 166:2001 1.FT	Lens Colour Product Code 2820 2821 2822
30	3M™ Tora™ Spectacles		Lenses and temples in combined colours intensify the contemporary smart look. 9D base curved lens offers excellent peripheral vision and perfect lateral side protection (Optical Class 1).	EN 166 1.F and EN 170 1.FT	Lens Colour Product Code
3M COMFORT SPECTACLES	3M [™] 2840 Series Spectacles		With a new, unique style the 3M™ 2840 Spectacles have been designed with user comfort and convenience in mind. The temples are fully inclinable and adjustable in length for optimal fit. The soft inner padding offers increased comfort. The 3M™ 2840 Spectacles feature a strong polycarbonate lens with anti-scratch and anti-fog coating (except 3M™ 2844) and integrated browguard.	EN 166 and EN 170 1.FT	Lens Colour Product Code
зм сомғо	3M [™] Solus [™] Spectacles		From colour-accented temples, to the high profile dual lens look of fashion street wear, Solus brings sophistication and comfort to safety eyewear.	EN 166 and EN 170 1.FT	Lens Colour Code Frame 71505-00001CP 71505-00002CP 71505-00003CP 71505-00004CP 71505-00005CP
ES	3M™ Eagle™ Spectacles		The Polycarbonate lens eliminates the UV, reduces IR levels and secures perfect eye comfort by controlling visible light. Can be used in all situations where UV, IR or visible light creates a risk. Available in shade 1,7 (welder's assistant) up to 7,0 (oxy cutting).	EN 166 1.F	Lens Colour Code Frame / Lens
PECTACL	3M [™] Metaliks [™] Spectacles	90	Polished metal frame with a sleek 10-base de-centered twin lens for optimum eye coverage and optimal field of vision.	EN 166 1.F and EN 170 1.F	Lens Colour Code Frame
3M PREMIUM SPECTACLE	3M [™] Metaliks [™] Sport Spectacles	\	Metal frames with saddle type nosepiece. Formable rubber tipped temples for extra comfort and adjustability.	EN 166 1.FT	Code Frame
31	3M™ Fuel™ X2 Series Spectacles		An ultra efficient blend of comfort and style offers a refined look and superb features.	EN 166 1.FT	Code Frame
GOGGLES	3M [™] 2890 Goggles	5	The 3M™ 2890 Safety Goggles feature a modern, slim design and are available with four options using an either acetate or polycarbonate lens with either sealed (3M™ 2890S, 3M™ 2890SA) or indirect ventilation	2890 + 2890S EN166 1.BT 2890A + 2890SA EN166 1.FT	Lens Colour Product Code 2890 2890A 2890S 2890SA
606	3M™ Fahrenheit Goggles		Soft PVC crystal frame with a wide support area all around the face to enhance comfort. Specific channel on the side of the frame to accommodate the temple of prescription frames.	EN166 1.BT EN166 1.BT EN166 1.B9	Lens Colour Product Code Headband Ventilation 71360-00001 Nylon Indirect 71360-00002 Nylon Indirect 71360-00005 Neoprene Non-vent



We do the Overtime - Care and Maintenance

Why is care and maintenance so important?

To optimise the effective lifetime of your welding protective equipment and avoid additional cost of replacement, regular maintenance is important.

Guidance on the appropriate checks is provided in the instruction booklets with each new system/item. The care and Maintenance Pack Sheets and Posters make this information accessible on a day-to-day basis and are a strong visual reminder.

Packs

The care and maintenance packs provide easy-to-follow guidance explaining the checks and procedures for the components of each 3M system on site. The use



of posters and information sheets allows this key information to become easily accessible to everyone involved with maintaining the equipment.

Information Sheets

The sheets highlight the main 'Before Use' and 'After Use' checks (as required) for each piece of kit. They also provide a breakdown of various consumables, accessories and repair parts with part numbers and pack quantities.



Posters

The A3 posters highlight the main 'Before Use' and 'After Use' checks required to ensure optimum performance and protection.



Record Cards

As part of the COSHH regulations relating to respiratory protective equipment, records of monthly checks must be kept.



To download the above material, please go to: www.3M.co.uk/maintenancepacks

To request full packs please call 3M Safety Services on **0845 601 3457**

3M Fit Testing

Do you have workers who wear tight fitting respirators, such as Disposable Respirators, Half Masks or Full Face Masks (including those fitted to a powered respirator)?

If so, you are required to fit test them*







Product Type	Required Fit Test Method
Disposable Respirator	Qualitative or Quantitative
Half Mask (including those fitted to a powered or supplied air device)	Qualitative or Quantitative
Full Face Mask (including those fitted to a powered or supplied air device)	Quantitative Only

3M can offer both Qualitative and Quantitative Fit Testing.

The 3M Fit Testing Service is provided by Fit2Fit accredited personnel on the employers site at a day/time suitable to the employer. The Fit2Fit accreditation scheme is a BSIF initiative supported by the HSE which ensures fit testers can conduct a fit test to the level of competence required in the HSE guidance note 282/28. Staff carrying out the testing are competent at fit testing and have a professional and friendly manner which is important when coaching and reassuring employees during their fit test.



We will fit test employees on the respirator that has been issued. We also carry sufficient samples of 3M's full range of respirators, so should any employee require a different model or design, samples are made available if required. 3M can offer a fit testing service lasting either half a day or a full day(s), depending on the number of employees who require a fit test.

*as per COSHH Regulations 2002

To receive a quote for Face Fit Testing, please either call our 3M Safety Services Coordinator on **0845 601 3457**, or email us on **safetyservices.uk@mmm.com**



3M Air Quality Testing Service

Do you use airfed respirators?

The COSHH regulations require that the air provided to this type of equipment should be of breathable quality and of sufficient, constant flow and pressure to provide adequate protection*

The 3M Air Quality Testing Service is carried out by engineers who will:

- Carry out a briefing where required, on the test procedure
- ✓ Test the air at several positions, as per your requirements
- Suggest measures and give sound advice, if the air does not meet the requirements, to enable the employer to make further assessments
- ✓ Issue a certificate should the air meet the requirements of Breathable Quality Air
- ✓ Issue a written set of test results
- Send an automatic notification for re-test as per your requirements



Air Quality Testing

An air quality test will check the oxygen level of the air and the level of the following contaminants:

√ oil
√ water
√ carbon dioxide
√ carbon monoxide
√ odour



Air Flow Testing

An air flow test ensures the air flow at each outlet meets the flow and pressure required by your respiratory protective equipment.

To receive a quote for Air Quality Testing services, please either call our 3M Safety Services Coordinator on **0845 601 3457**, or email us on **safetyservices.uk@mmm.com**

*as per COSHH Regulations 2002 (European Standard for Breathable Quality air is EN12021).

3M Health and Safety Helpline - 0870 60 800 60 (UK), 1 800 320 500 (Ireland)

Diverse range of personal protective equipment

The combined portfolio of $3M^{\text{\tiny{TM}}}$, Peltor and E·A·R products includes high-quality, innovative solutions to protect people at work. Here are some examples:

Respiratory protection







Hearing protection







Eye protection







Head protection





Welding protection

Protective coveralls







For more information about our products and services visit our website at www.3M.co.uk/ohes



3M Welding 3M United Kingdom plc 3M Centre Cain Road, Bracknell Berkshire RG12 8HT Tel: 0161 237 6104 www.3M.co.uk/speedglas

3M Welding 3M Ireland Limited The Iveagh Building The Park Carrickmines Dublin 18 Tel: 1800 320 500

13261 Please recycle. Printed in the United Kingdom. © 3M 2011. All rights reserved. CHWELDINGDIRECTORY.Iss 1